

HOMOLOGATION AND TECHNICAL SPECIFICATION UPDATE BULLETIN

HOMOLOGATION	Rotax 125 Senior Max	HOMOLOGATION NO.	113H
BULLETIN NO.	Rotax 21	BULLETIN DATE	9 December 2016
SUBJECT	Wiring Harness for 125 Senior Max		

The information and specifications contained in this Homologation and Technical Specification Update Bulletin are to be read in conjunction with and form part of the homologation detailed herein.

EXPLANATORY NOTES SUPPLIED BY THE MANUFACTURER'S REPRESENTATIVE.

Homologation Document Reference: Rotax 125 Senior Max, Rule B11.3.6, Page 53

Heading: Dellorto Ignition System



Details:

The new wiring harness creates less electrical connections at the backside of the engine.

- (1) Plug in connection for the multifunction switch
- (2) The connector for charging the battery is directly fixed to the wiring harness
- (3) The plug in connection for the e-starter incorporates the ground connection for the total electrical system (no separate ground cable necessary).
- (4) The ground connection for selection of the exhaust valve timing is located below the battery cover.

