

# HOMOLOGATION AND TECHNICAL SPECIFICATION UPDATE BULLETIN

HOMOLOGATION	125 MICRO MAX 125 MINI MAX 125 JUNIOR MAX 125 SENIOR MAX 125 MAX DD2	HOMOLOGATION NO's.	110H 111H 112H 113H 114H
BULLETIN NO.	Rotax 31 - All Engines	BULLETIN DATE	2 June 2017
SUBJECT	<b>IGNITION PICK UP SENSOR GASKET</b>		

The information and specifications contained in this Homologation and Technical Specification Update Bulletin are to be read in conjunction with and form part of the homologation detailed herein.

---

### EXPLANATORY NOTES SUPPLIED BY THE MANUFACTURER'S REPRESENTATIVE.

If a Dellorto Ignition System is used, a Rotax gasket (Part No. 431 500) is a legal specification that can fitted between the Ignition Pick Up Sensor and the rubber sealing ring of the sensor.

**The gasket thickness = 0.8mm +/- 0.1mm**

Maximum two gaskets are allowed to be fitted.

The increased distance from the Crankshaft to the Ignition Pick Up Sensor reduces the signal magnitude, and the ECU will filter any incorrect signals that may cause a misfire.

### Homologation Document Reference

**Section:** DELLORTO IGNITION SYSTEM



**Details:**

